



F1 = 350 (11350)				
E	G	H	I	L
72	1100	700	1450	2317
78	1080	700	1430	2361
88	1115	700	1465	2445
92	1080	700	1430	2317

F2 = 550 (11550)				
E	G	H	I	L
72	1300	900	1650	2517
78	1280	900	1630	2561
88	1315	900	1665	2645
92	1280	900	1630	2517

F3 = 800 (11800)				
E	G	H	I	L
72	1550	1150	1900	2767
78	1530	1150	1880	2811
88	1565	1150	1915	2895
92	1530	1150	1880	2767